

AD-A134 751 FORM COEFFICIENT FOR THE FIELD OF A SUPERCONDUCTING  
SYNCHRONOUS MACHINE(U) FOREIGN TECHNOLOGY DIV  
WRIGHT-PATTERSON AFB OH A I BERTINOV ET AL. 21 OCT 83


1/1

UNCLASSIFIED FTD-ID(RS)T-1132-83

F/G 20/3

NL

END  
DATE  
FILED  
12-83  
DTIC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS - 1963 - A

(2)

FTD-ID(RS)T-1132-83

AD-A134 751



## FOREIGN TECHNOLOGY DIVISION



FORM COEFFICIENT FOR THE FIELD OF A SUPERCONDUCTING  
SYNCHRONOUS MACHINE

by

A. I. Bertinov, A. V. Golovkin, et al.



Approved for public release;  
distribution unlimited.

DTIC FILE COPY



83 11 16 105

# EDITED TRANSLATION

FTD-ID(RS)T-1132-83

21 October 1983

MICROFICHE NR: FTD-83-C-001281

FORM COEFFICIENT FOR THE FIELD OF A SUPERCONDUCTING  
SYNCHRONOUS MACHINE

By: A. I. Bertinov, A. V. Golovkin, et al.

English pages: 8

Source: Elektrotehnika, Nr. 1, January 1970,  
pp. 43-46

Country of origin: USSR

Translated by: Charles T. Oster-tag, Jr.

Requester: FTD/TQTD

Approved for public release; distribution unlimited.

Accession For	
NTIS GRA&I	
DTIC TAB	
Unpublished	
Justification	
Py	
DD FORM 1417, 1 APR 73	
1	
2	
3	
4	
5	
6	
7	
8	
9	
A-1	



THIS TRANSLATION IS A RENDITION OF THE ORIGINAL FOREIGN TEXT WITHOUT ANY ANALYTICAL OR EDITORIAL COMMENT. STATEMENTS OR THEORIES ADVOCATED OR IMPLIED ARE THOSE OF THE SOURCE AND DO NOT NECESSARILY REFLECT THE POSITION OR OPINION OF THE FOREIGN TECHNOLOGY DIVISION.

PREPARED BY:

TRANSLATION DIVISION  
FOREIGN TECHNOLOGY DIVISION  
WP-AFB, OHIO.

FTD-ID(RS)T-1132-83

Date 21 Oct 19 83

U. S. BOARD ON GEOGRAPHIC NAMES TRANSLITERATION SYSTEM

Block	Italic	Transliteration	Block	Italic	Transliteration
А а	А а	А, a	Р р	Р р	Р, r
Б б	Б б	Б, b	С с	С с	С, s
В в	В в	В, v	Т т	Т т	Т, t
Г г	Г г	Г, g	Ү ү	Ү ү	Ү, u
Д д	Д д	Д, d	Ф ф	Ф ф	Ф, f
Е е	Е е	Ye, ye; Э, e*	Х х	Х х	Хх, kh
Ж ж	Ж ж	Zh, zh	Ц ц	Ц ц	Ts., ts
З з	З з	Z, z	Ч ч	Ч ч	Ch, ch
И и	И и	I, i	Ш ш	Ш ш	Sh, sh
Й ю	Й ю	Y, y	Щ щ	Щ щ	Shch, shch
К к	К к	K, k	Ь ъ	Ь ъ	"
Л л	Л л	L, l	Ҥ ҥ	Ҥ ҥ	Y, y
М м	М м	M, m	Ծ Ծ	Ծ Ծ	'
Н н	Н н	N, n	Э э	Э э	E, e
О о	О о	O, o	Ւ Ւ	Ւ Ւ	Yu, yu
П п	П п	P, p	Я я	Я я	Ya, ya

\*ye initially, after vowels, and after ъ, ѕ; ё elsewhere.  
When written as ё in Russian, transliterate as yё or ё.

RUSSIAN AND ENGLISH TRIGONOMETRIC FUNCTIONS

Russian	English	Russian	English	Russian	English
sin	sin	sh	sinh	arc sh	$\sinh^{-1}$
cos	cos	ch	cosh	arc ch	$\cosh^{-1}$
tg	tan	th	tanh	arc th	$\tanh^{-1}$
ctg	cot	cth	coth	arc cth	$\coth^{-1}$
sec	sec	sch	sech	arc sch	$\sech^{-1}$
cosec	csc	csch	csch	arc csch	$\operatorname{csch}^{-1}$

Russian	English
rot	curl
lg	log

GRAPHICS DISCLAIMER

All figures, graphics, tables, equations, etc.  
merged into this translation were extracted  
from the best quality copy available.

## FORM COEFFICIENT FOR THE FIELD OF A SUPERCONDUCTING SYNCHRONOUS MACHINE

A. I. Bertinov, Professor, Doctor of Technical Sciences  
A. V. Golovkin, Engineer  
L. A. Yegoshkina, Engineer  
O. M. Mironov, Candidate of Technical Sciences

The magnetic field of a superconducting synchronous machine is considered, an expression unique for all areas, is obtained for the radial component of intensity of the magnetic field, and the form coefficient of the field is determined.

The industrial assimilation of superconducting materials with high values of critical magnetic field led to the development of magnetic systems which can be used for excitation of electrical machines [1].

The use of superconductor excitation windings for synchronous machines leads to new structural arrangements for making them, and the absence of a ferromagnetic magnetic circuit complicates the picture of distribution of the magnetic field. What was said requires the refinement of the bases of the theory and methods of designing superconducting machines.

In [2] a magnetic field is considered which is created by the superconductor excitation winding of a synchronous machine, and in this case the component of strength of the magnetic field is presented in the form of infinite series, and only the first harmonic component is analyzed, which is not always justified.

A significant shortcoming of work [2] is that for each zone of the system its own expressions are obtained: inside the system, in the zone occupied by currents, and outside the excitation system. The absence of a generality - a unique expression - complicates their use, especially in the case of calculation on a digital computer.

In the present work a unique expression is obtained for finding the radial component of strength of a magnetic field in a finite form, and the form coefficient is determined for the field of a superconducting synchronous machine.

Let us consider the magnetic system of excitation of a synchronous machine which is shown in Figure 1. The problem of determination of the components of the vector of strength of the magnetic field in all the points of space in respect to an assigned distribution of current is solved by finding the vector potential of the magnetic field as a function of the coordinates:

$$\begin{aligned} A &= \frac{\mu_0}{2\pi} \int_{r_0}^r \frac{Idv}{a}, \\ H &= \frac{1}{\mu_0} \operatorname{rot} A. \end{aligned} \quad (1)$$

In solving the problem the following assumptions are accepted: the magnetic field is plane-parallel, i.e., the finite length of the excitation system is not taken into account; the magnetic permeability of the superconducting material of the excitation winding is constant and equal to  $\mu_0$ , since the superconducting materials in magnetic systems operate with fields which are close to critical; the area occupied by currents is uniform.

Then in a cylindrical system of coordinates the axial component of the vector potential function in point  $P(r, \varphi)$  from the elementary conductor with current, found in point  $M(r, \varphi_0)$ , is equal to

$$A = -\frac{\mu_0}{2\pi} j_0 r d\varphi dr \ln a. \quad (2)$$

where  $a = \sqrt{r^2 + r_0^2 - 2rr_0 \cos(\varphi - \varphi_0)}$ .

$i_{sp} = \frac{I}{q_{s.s.}} k_{s.s.}$  - average calculated density of current;  
 $I$  - current, passing on a conductor;  
 $q_{s.s.}$  - area of the transverse section of  
 the superconducting conductor;  
 $k_{s.s.} = \frac{q_{s.s.} w}{q_{06}}$  - space factor of the superconductor  
 in the excitation winding;  
 $w$  - number of turns in the winding;  
 $q_{06}$  - area of transverse section occupied  
 by the excitation winding.




Figure 1. Excitation winding of a superconductor synchronous machine.

The radial component of strength of the magnetic field from an elementary conductor with current

$$H'_r = \frac{1}{\mu_0 r} \frac{\partial A}{\partial \varphi} = - \frac{i_{sp} r^2 \sin(\varphi - \varphi_0) dr d\varphi_0}{2\pi [r^2 + r'^2 - 2pr \cos(\varphi - \varphi_0)]}. \quad (3)$$

Let us integrate on the entire section occupied by the individual coils with current, with a calculation of the number of pairs of poles

$p$  and  $r = \frac{\pi - 2\theta}{\pi}$  :

$$\begin{aligned}
 H_p &= - \frac{i_{sp}}{2\pi} \sum_{k=1}^{k=2p} (-1)^{k+1} \times \\
 &\times \int_{\frac{D_1}{2}}^{\frac{D_2}{2}} \int_{\frac{k-1}{p} + \frac{1-\theta}{2}}^{\frac{k}{p} - \frac{1-\theta}{2}} \frac{r^2 \sin(\varphi - \varphi_0)}{r^2 + r'^2 - 2pr \cos(\varphi - \varphi_0)} dr d\varphi_0. \quad (4)
 \end{aligned}$$

After integration, replacement of  $\rho = D/2$  and introduction for convenience of subsequent calculations and construction of the graphic dependences of relative dimensions

$$\hat{D}_1 = \frac{D_1}{D}; \hat{D} = \frac{D}{D_1}$$

we obtain:

$$H_p = \frac{I_{sp} D_1}{8\pi} K_p,$$

where the coefficient

$$\begin{aligned}
 K_p = & \sum_{k=1}^{k=2p} (-1)^{k+1} \left[ \frac{1}{2\hat{D}} \ln \frac{\hat{D}^2 + 1 - 2\hat{D}\cos\alpha}{\hat{D}^2 + 1 - 2\hat{D}\cos\beta} - \right. \\
 & - \frac{\hat{D}_1^2}{2\hat{D}} \ln \frac{\hat{D}^2 + \hat{D}_1^2 - 2\hat{D}\hat{D}_1\cos\alpha}{\hat{D}^2 + \hat{D}_1^2 - 2\hat{D}\hat{D}_1\cos\beta} - \hat{D} \left( \cos^2\alpha - \frac{1}{2} \right) \times \\
 & \times \ln \frac{\hat{D}^2 + 1 - 2\hat{D}\cos\alpha}{\hat{D}_1^2 - 2\hat{D}\hat{D}_1\cos\alpha} + \hat{D} \left( \cos^2\beta - \frac{1}{2} \right) \times \\
 & \times \ln \frac{\hat{D}^2 + 1 - 2\hat{D}\cos\beta}{\hat{D}^2 + \hat{D}_1^2 - 2\hat{D}\hat{D}_1\cos\beta} + (1 - \hat{D}_1)(\cos\beta - \cos\alpha) + \\
 & + \hat{D}\sin 2\alpha \left( \operatorname{arctg} \frac{1 - \hat{D}\cos\alpha}{\hat{D}\sin\alpha} - \operatorname{arctg} \frac{\hat{D}_1 - \hat{D}\cos\alpha}{\hat{D}\sin\alpha} \right) - \\
 & - \hat{D}\sin 2\beta \left( \operatorname{arctg} \frac{1 - \hat{D}\cos\beta}{\hat{D}\sin\beta} - \operatorname{arctg} \frac{\hat{D}_1 - \hat{D}\cos\beta}{\hat{D}\sin\beta} \right); \\
 & \alpha = \varphi - \pi \left( \frac{k}{p} - \frac{1-\gamma}{2} \right); \beta = \varphi - \pi \left( \frac{k-1}{p} + \frac{1-\gamma}{2} \right). \tag{5}
 \end{aligned}$$

Expression (5) is valid for any point of the area under consideration.

For determination of the form coefficient of the field it is necessary to have an expression for the maximum of the radial component of magnetic field strength, which will be in the case of the angle  $\varphi = 0$ , in this case

$$\alpha = -\pi \left( \frac{k}{p} - \frac{1-\gamma}{2} \right); \beta = -\pi \left( \frac{k-1}{p} + \frac{1-\gamma}{2} \right).$$

With complete filling of the active layer by the winding  $\theta = 0$  and  $\gamma = 1$ . In this case

$$\alpha = -\frac{\pi k}{p} \text{ and } \beta = \alpha + \frac{\pi}{p}.$$

Thus, with  $\gamma = 1$  and different numbers of pairs of poles it is possible to write:

when  $p=1$

$$K_p = \frac{2}{\dot{D}} (1 - \dot{D}^2) \ln \frac{\dot{D} + 1}{\dot{D} - 1} - \frac{2}{\dot{D}} (\dot{D}_1^2 - \dot{D}^2) \ln \frac{\dot{D} + \dot{D}_1}{\dot{D} - \dot{D}_1} + \\ + 4 (1 - \dot{D}_1);$$

when  $p=2$

$$K_p = \frac{2}{\dot{D}} \ln \frac{\dot{D}^2 + 1}{\dot{D}^2 - 1} - \frac{2 \dot{D}_1^2}{\dot{D}} \ln \frac{\dot{D}^2 + \dot{D}_1^2}{\dot{D}^2 - \dot{D}_1^2} + \\ + 2 \dot{D} \ln \frac{\dot{D}^4 - 1}{\dot{D}^4 - \dot{D}_1^4};$$

when  $p=3$

$$K_p = \frac{1}{\dot{D}} (1 + \dot{D}^3) \ln \frac{\dot{D}^3 + 1}{\dot{D}^3 - 1} + 3 \dot{D} \ln \frac{\dot{D} - 1}{\dot{D} + 1} - \\ - \frac{1}{\dot{D}} (2 \dot{D}_1^2 + \dot{D}^2) \ln \frac{\dot{D}^3 + \dot{D}_1^3}{\dot{D}^3 - \dot{D}_1^3} - 3 \dot{D} \ln \frac{\dot{D} - \dot{D}_1}{\dot{D} + \dot{D}_1} + \\ + 2 \sqrt[3]{\dot{D}} \left[ \operatorname{arctg} \frac{2 - \dot{D}}{\sqrt[3]{\dot{D}}} + \operatorname{arctg} \frac{2 + \dot{D}}{\sqrt[3]{\dot{D}}} - \right. \\ \left. - \operatorname{arctg} \frac{2 \dot{D}_1 - \dot{D}}{\sqrt[3]{\dot{D}}} - \operatorname{arctg} \frac{2 \dot{D}_1 + \dot{D}}{\sqrt[3]{\dot{D}}} \right];$$

when  $p=4$

$$K_p = \frac{2}{\dot{D}} \ln \frac{\dot{D}^4 + 1}{\dot{D}^4 - 1} + 2 \dot{D} \ln \frac{\dot{D}^4 - 1}{\dot{D}^4 + 1} - \\ - \frac{2 \dot{D}_1^2}{\dot{D}} \ln \frac{\dot{D}^4 + \dot{D}_1^4}{\dot{D}^4 - \dot{D}_1^4} + 2 \dot{D} \ln \frac{\dot{D}^4 + \dot{D}_1^2}{\dot{D}^4 - \dot{D}_1^2} + \\ + 4 \dot{D} \left[ \operatorname{arctg} \frac{2 - \sqrt{2} \dot{D}}{\sqrt{2} \dot{D}} - \operatorname{arctg} \frac{2 + \sqrt{2} \dot{D}}{\sqrt{2} \dot{D}} - \operatorname{arctg} \frac{2 \dot{D}_1 - \sqrt{2} \dot{D}}{\sqrt{2} \dot{D}} + \right. \\ \left. + \operatorname{arctg} \frac{2 \dot{D}_1 + \sqrt{2} \dot{D}}{\sqrt{2} \dot{D}} \right].$$

The dependences  $K_p = f(D^* \text{ and } D_1^*)$  in respect to  $p$  are given in Figure 2. Coefficient  $K_p$  is proportional to the radial component of magnetic field strength, and from these graphs it follows that the radial component of magnetic field strength has the greatest value inside the area occupied by the excitation winding. With the same dimensions of the excitation winding the maximum value of magnetic field strength which is obtained is greater in two-pole machines and is reduced with an increase in the number of pairs of poles of the excitation winding.

Using (5) and having assigned the dimensions of the excitation winding and the armature, it is possible to determine the emf induced in the armature winding. As it follows from [2], the amplitude of the curve of the harmonic component of magnetic field intensity is expressed for different areas with  $\gamma=1$ :

for

$$\hat{D} < \hat{D}_1$$

$$H_{p1m} = \frac{i_c p D_2}{8\pi} \frac{8(1 - \hat{D}_1^{-p+2})}{(2-p)\hat{D}^{-p+1}};$$

for

for

$$\hat{D}_1 < \hat{D} < 1$$

$$H_{p1m} = \frac{i_c p D_2}{8\pi} \frac{8\hat{D}}{4-p^2} \left[ -2p + \frac{2+p}{\hat{D}^{-p+2}} - \frac{(2-p)\hat{D}^{p+2}}{\hat{D}^{p+2}} \right] \hat{D};$$

$$1 < \hat{D} \\ H_{p1m} = \frac{i_c p D_2}{8\pi} \frac{8(1 - \hat{D}_1^{p+2})}{(p+2)\hat{D}^{p+1}}.$$

Thus it is possible to determine the form coefficient for the field of a superconductor machine with  $\gamma=1$ :

$$K_f = \frac{H_{p1m=0}}{H_{p=0}},$$

shown in Figures 3 and 4 in dependence on  $D$  and  $D_1$  for different numbers of pairs of poles.

An analysis of the graphs in Figures 3 and 4 shows that the ratio of the maximum of magnetic field strength to the amplitude of the first harmonic component reaches 1.8, therefore disregard of the higher harmonic components, especially in the case of calculation inside the coil, is inadmissible.







Figure 2. Dependence of  $K_p = f^*(D)$  in respect to  $D_1$ .

a -  $p = 1$ ; b -  $p = 2$ ; c -  $p = 3$ ; d -  $p = 4$ .




Figure 3. Dependence of  $K_f = f(D)$  in respect to  $D_1$  when  $p=1$ .




Figure 4. Dependence of  $K_f = f(D)$  in respect to  $p$  when  $D_1 = 0.6$ .

Conclusions.

1. A unique expression is obtained for the radial component of magnetic field strength for any area of a system of excitation.
2. The form coefficient of the field of the excitation winding is obtained.
3. Analysis showed the considerable magnitude of the higher harmonic components of magnetic field strength in the area occupied by currents.

REFERENCES

1. Е. Я. Казовский, В. П. Карцев. Применение сверхпроводников для возбуждения электрических машин. «Электротехника», 1964, № 6.
2. H. H. Woodson, J. J. Stekly, E. Halas. Power Apparatus and Systems, 1966, v. 85, № 3.

